


OSN Pod Baremetal Provisioning Sequence (Layer 3)



1. [Site] Power-on mon2 and all switches.
2. [CC] Push switch and PDU configurations via SSH tunnel.
3. [Site] Power-on remaining server nodes.
4. [Auto] Red Hat kickstart installation.
5. [CC] Ansible completes pod setup via SSH tunnel and installs OSN software stack.